



URGENT FIELD SAFETY NOTICE: RA2019 - 2144473

FSCA identifier: 2144473
Type of Action: Field Safety Corrective Action: Recall
Legal Manufacturer: Howmedica Osteonics Corp. 325 Corporate Drive. 07430 Mahwah, N.J. USA

Product Affected:

Catalog Number	Description	Lot number
5541-A-201	TRIATHLON FEMORAL DISTAL AUGMENT 10MM - SIZE 2 LEFT	See attached
5541-A-202	TRIATHLON FEMORAL DISTAL AUGMENT 10MM - SIZE 2 RIGHT	See attached
5542-A-201	TRIATHLON FEMORAL DISTAL AUGMENT 15MM - SIZE 2 LEFT	See attached
5542-A-202	TRIATHLON FEMORAL DISTAL AUGMENT 15MM - SIZE 2 RIGHT	See attached

August XX, 2019

Dear Customer,

Stryker has initiated a voluntary, lot-specific recall for the Triathlon Femoral Distal Augment, 10 mm – Size 2 Left, Triathlon Distal Augment 10 mm – Size 2 Right, Triathlon Femoral Distal Augment 15 mm – Size 2 Left and Triathlon Distal Augment 15 mm – Size 2 Right. The intent of this letter is to list known hazards and harms potentially associated with the above referenced products and list any risk mitigation factors.

Issue:

Stryker has discovered that the above-mentioned Triathlon Femoral Distal Augments (10 and 15 mm, Size 2, Left and Right) protrude beyond the medial periphery of the mating femoral component.

Triathlon Femoral Distal Augments are used with the Triathlon TS Femoral Component during a Total Knee Arthroplasty (TKA) Revision procedure or with a Triathlon Primary PS Femoral Component during a TKA procedure.

Potential Hazards:

If a Triathlon Femoral Distal Augment Size 2, 10 or 15 MM is used with the Triathlon TS Femoral Component during a Total Knee Arthroplasty (TKA) Revision procedure or with a Triathlon Primary PS Femoral Component during a TKA procedure, the following potential hazards may occur:

- The distal augment overhang could potentially result in the exposed edge contacting the soft tissue surrounding the medial condyle
- Metallic debris in wound
- Sharp/abrasive corner of the overhanging distal augment



Potential Harms:

The aforementioned hazards may result in the following potential harm(s):

- Complications associated with extended surgery time of 20 minutes while retrieving a replacement Distal Augment
- Metal debris in wound may cause local inflammation or synovitis
- Tissue damage
- Pain requiring revision surgery

Risk Mitigation:

1. Medial overhang of the Triathlon Femoral Distal Augment Size 2, 10 or 15 MM should be obvious to the surgeon during assembly to its mating femoral component, potentially reducing the probability of implanting the device.
2. Larger bone on medial side of the femur may prevent the Triathlon Femoral Distal Augment Size 2, 10 or 15 MM from overhang past resected bone.

Actions Needed:

Our records indicate that you have received at least one of the subject devices and you are therefore affected by this action.

We request that you read this notice carefully and complete the following actions:

1. Immediately check your internal inventory and quarantine all subject devices pending to return to Stryker.
2. Circulate this Field Safety Notice internally to all interested/affected parties.
3. Maintain awareness of this notice internally until all required actions have been completed within your facility.
4. Inform Stryker if any of the subject devices have been distributed to other organizations.
 - a) Please provide contact details so that Stryker can inform the recipients appropriately.
 - b) If you are a Distributor, note that you are responsible for notifying your affected customers.
5. Please inform Stryker of any adverse events concerning the use of the subject devices.

Please comply with any local regulations concerning the notification of adverse events to your National or local Competent Authorities.

6. Complete the attached customer response form. It may be that you no longer have any physical inventory on site. Completing this form will allow us to update our records and will



also negate the need for us to send any further unnecessary communications on this matter. Therefore please complete even if you longer have any of the subject devices in your physical inventory.

7. Return the completed form to your nominated Stryker Representative (indicated below) for this PFA.
 - a. On receipt of the form, a Stryker Representative will contact you to organize any applicable ongoing actions.

We request that you respond to this notice within 7 calendar days from the date of receipt.

Your designated contact person for this action is given below. Should you have any queries concerning this matter please do not hesitate to contact them directly.

Name:
Position:
Telephone:
E-mail:

In line with the recommendations of the Meddev Vigilance Guidance document Ref.2.12-1, we can confirm that this FSCA has been notified appropriately to the National Competent Authority for your country.

On behalf of Stryker we thank you sincerely for your help and support in completing this action within the target date and regret any inconvenience that may be cause. We would like to reassure you that Stryker is committed to ensuring that only conforming devices, meeting our high internal quality standards, remaining on the market.

Yours Sincerely,



URGENT FIELD SAFETY NOTICE: RA2019 - 2144473
Acknowledgment form

FSCA identifier: 2144473
Type of Action: Field Safety Corrective Action: Recall
Legal Manufacturer: Howmedica Osteonics Corp. 325 Corporate Drive. 07430 Mahwah, N.J. USA
Product Affected:

Catalog Number	Description	Lot number
5541-A-201	TRIATHLON FEMORAL DISTAL AUGMENT 10MM - SIZE 2 LEFT	See attached
5541-A-202	TRIATHLON FEMORAL DISTAL AUGMENT 10MM - SIZE 2 RIGHT	See attached
5542-A-201	TRIATHLON FEMORAL DISTAL AUGMENT 15MM - SIZE 2 LEFT	See attached
5542-A-202	TRIATHLON FEMORAL DISTAL AUGMENT 15MM - SIZE 2 RIGHT	See attached

I acknowledge receipt of the Field Safety Notice for RA2019-2067376 and can confirm that:

We have not located any of these devices in our inventory: (please delete if not applicable)				
We have located the following devices:				
Catalog number	Description	Lot number	Qty	
We have further distributed subject devices to the following organizations:				
Facility Name				
Facility Address				
Please sign and return this form to acknowledge receipt of product notice.				
Name of Hospital / Organisation		Department		
Contact Name		Address		
Contact Title				
Contact Signature		E-mail Address		
Contact Phone No.		Date		

PLEASE COMPLETE THIS FORM WITHIN 5 BUSINESS DAYS AND RETURN IT BY USING THE EMAIL, **XX, OR FAX, **XX**.**



URGENT FIELD SAFETY NOTICE: RA2019 - 2144473

Attachment: List of affected lots

Catalog Number	Lot	Catalog Number	Lot	Catalog Number	Lot	Catalog Number	Lot
5541-A-201	A3A4G	5541-A-201	BLL9A	5541-A-201	IBZA	5541-A-201	MDZU
5541-A-201	A3O4G	5541-A-201	BRE9E	5541-A-201	IDZV	5541-A-201	MLWL
5541-A-201	A7E4A	5541-A-201	BRO7U	5541-A-201	IKGT	5541-A-201	MNKY
5541-A-201	A7S7Y	5541-A-201	BRY4Y	5541-A-201	IKKM	5541-A-201	MOHT
5541-A-201	AABP	5541-A-201	BS97E	5541-A-201	ILHJ	5541-A-201	MPNI
5541-A-201	AABR	5541-A-201	BSH7H	5541-A-201	INIM	5541-A-201	MROZ
5541-A-201	AAS7L	5541-A-201	BSO3G	5541-A-201	INLE	5541-A-201	S3HR
5541-A-201	ABI3L	5541-A-201	BTE4D	5541-A-201	ITMY	5541-A-201	SSVR
5541-A-201	ABY7A	5541-A-201	DNVL	5541-A-201	IXNB	5541-A-201	TGOB
5541-A-201	AE44H	5541-A-201	DRSG	5541-A-201	IYRK	5541-A-201	U3BV
5541-A-201	AEB7H	5541-A-201	DVXW	5541-A-201	JBOV	5541-A-201	ULIO
5541-A-201	AER7Y	5541-A-201	DZKF	5541-A-201	JDJY	5541-A-201	USUR
5541-A-201	AGS7H	5541-A-201	FUXX	5541-A-201	JEUD	5541-A-201	UZYY
5541-A-201	AHS4D	5541-A-201	FVAH	5541-A-201	JIOX	5541-A-201	V4ZD
5541-A-201	AIA7Y	5541-A-201	GARO	5541-A-201	JIYT	5541-A-201	VADL
5541-A-201	AII4Z	5541-A-201	GAWP	5541-A-201	JJZE	5541-A-201	VGLG
5541-A-201	ALR4L	5541-A-201	GBTP	5541-A-201	JKFX	5541-A-201	VHWH
5541-A-201	AOU3R	5541-A-201	GJZD	5541-A-201	JKYF	5541-A-201	VJHI
5541-A-201	ARG9T	5541-A-201	GKAJ	5541-A-201	JLIF	5541-A-201	VJYL
5541-A-201	ASZ3O	5541-A-201	GKDW	5541-A-201	JOJF	5541-A-201	VPSZ
5541-A-201	ATG4X	5541-A-201	GLAN	5541-A-201	JWEF	5541-A-201	VRDA
5541-A-201	ATU7D	5541-A-201	GLBU	5541-A-201	JWVL	5541-A-201	VTYL
5541-A-201	AVG7Z	5541-A-201	GLHI	5541-A-201	JYWU	5541-A-201	VWRZ
5541-A-201	AVO9H	5541-A-201	GLHY	5541-A-201	JZYF	5541-A-201	VZVT
5541-A-201	AYG9Y	5541-A-201	HHRP	5541-A-201	KEXO	5541-A-201	WDVE
5541-A-201	AYX3Y	5541-A-201	HHVI	5541-A-201	KMFK	5541-A-201	WIRA
5541-A-201	BAE3E	5541-A-201	HXGO	5541-A-201	KMGH	5541-A-201	WISA
5541-A-201	BAU3L	5541-A-201	HXML	5541-A-201	KMIS	5541-A-201	WOTL
5541-A-201	BE93T	5541-A-201	HXUV	5541-A-201	KOHJ	5541-A-201	WOUL
5541-A-201	BEB4L	5541-A-201	HYHY	5541-A-201	KPNX	5541-A-201	WRUR
5541-A-201	BGU4G	5541-A-201	HZBN	5541-A-201	KRPW	5541-A-201	WRUS
5541-A-201	BHL9O	5541-A-201	HZKZ	5541-A-201	KSNI	5541-A-201	WVZO
5541-A-201	BIE7H	5541-A-201	HZNH	5541-A-201	KUZR	5541-A-201	WWEP
5541-A-201	BL74I	5541-A-201	IBSA	5541-A-201	KVYS	5541-A-201	WXTS



Catalog Number	Lot	Catalog Number	Lot	Catalog Number	Lot	Catalog Number	Lot
5541-A-201	WXTT	5541-A-201	XLRY	5541-A-201	XWVJ	5541-A-201	YFXP
5541-A-201	WXTU	5541-A-201	XLRZ	5541-A-201	XWWZ	5541-A-201	YFXR
5541-A-201	WZP3	5541-A-201	XSFN	5541-A-201	XYGU	5541-A-201	YGDI
5541-A-201	XEMZ	5541-A-201	XSFP	5541-A-201	XYGV	5541-A-201	YGDZ
5541-A-201	XENA	5541-A-201	XSZE	5541-A-201	YBJJ	5541-A-201	YHDM
5541-A-201	XHZU	5541-A-201	XSZF	5541-A-201	YBJK	5541-A-201	YHDN
5541-A-201	XKWY	5541-A-201	XVJA	5541-A-201	YCZR	5541-A-201	
5541-A-201	XKWZ	5541-A-201	XVKZ	5541-A-201	YCZS	5541-A-201	
5541-A-202	A3E7R	5541-A-202	BBE4R	5541-A-202	GZNA	5541-A-202	JVEZ
5541-A-202	A3H9I	5541-A-202	BBL4Y	5541-A-202	GZRT	5541-A-202	JZSI
5541-A-202	A7A9A	5541-A-202	BDZ9H	5541-A-202	GZWG	5541-A-202	KFYW
5541-A-202	A9U7R	5541-A-202	BER7H	5541-A-202	GZWS	5541-A-202	KHHJ
5541-A-202	AB37T	5541-A-202	BH97L	5541-A-202	HHXY	5541-A-202	KHNX
5541-A-202	AB74U	5541-A-202	BLY9D	5541-A-202	HHZF	5541-A-202	KHSO
5541-A-202	ABB7S	5541-A-202	BO77U	5541-A-202	HHZZ	5541-A-202	KMEX
5541-A-202	AE49B	5541-A-202	BRR9H	5541-A-202	HIBF	5541-A-202	KSPV
5541-A-202	AES9B	5541-A-202	BRT7Z	5541-A-202	HUPS	5541-A-202	KVRZ
5541-A-202	AGAR	5541-A-202	BSI4X	5541-A-202	HVBW	5541-A-202	KVVS
5541-A-202	AGAS	5541-A-202	BTD9B	5541-A-202	HYHG	5541-A-202	KWPV
5541-A-202	AGB3E	5541-A-202	DGFR	5541-A-202	HYJB	5541-A-202	KYND
5541-A-202	AGT4E	5541-A-202	DGPY	5541-A-202	IBTS	5541-A-202	KZYB
5541-A-202	AGV3G	5541-A-202	DNUW	5541-A-202	IBTW	5541-A-202	MEDM
5541-A-202	AH37L	5541-A-202	DOFW	5541-A-202	IEVY	5541-A-202	MFZX
5541-A-202	AIO4V	5541-A-202	DRFR	5541-A-202	ILAX	5541-A-202	MGLY
5541-A-202	AO74U	5541-A-202	DRPA	5541-A-202	ILBL	5541-A-202	MLBP
5541-A-202	AOD9I	5541-A-202	DYEK	5541-A-202	INJO	5541-A-202	MMFV
5541-A-202	ARO9B	5541-A-202	DYRN	5541-A-202	INNB	5541-A-202	NEBU
5541-A-202	ASV7B	5541-A-202	EDHL	5541-A-202	INNE	5541-A-202	S3HS
5541-A-202	ATA9R	5541-A-202	FNYJ	5541-A-202	IUWT	5541-A-202	SOBP
5541-A-202	ATY3T	5541-A-202	FOGV	5541-A-202	IVAB	5541-A-202	SPO4
5541-A-202	AU99O	5541-A-202	FVVR	5541-A-202	IYLR	5541-A-202	SR4E
5541-A-202	AUX7R	5541-A-202	FYST	5541-A-202	JBYI	5541-A-202	TGGA
5541-A-202	AY33Z	5541-A-202	FYTP	5541-A-202	JFGV	5541-A-202	TIYY
5541-A-202	AYO4V	5541-A-202	GFPG	5541-A-202	JFNZ	5541-A-202	TPPH
5541-A-202	BAA4S	5541-A-202	GJMG	5541-A-202	JHDR	5541-A-202	TPTI
5541-A-202	BAB7Y	5541-A-202	GJNM	5541-A-202	JIKH	5541-A-202	UHIP
5541-A-202	BAH3D	5541-A-202	GYOD	5541-A-202	JILH	5541-A-202	USLI
5541-A-202	BAI7D	5541-A-202	GYVG	5541-A-202	JNIX	5541-A-202	UT3I



Catalog Number	Lot	Catalog Number	Lot	Catalog Number	Lot	Catalog Number	Lot
5541-A-202	UZDD	5541-A-202	WGRG	5541-A-202	XDYL	5541-A-202	XWVK
5541-A-202	V4AH	5541-A-202	WO4G	5541-A-202	XDYM	5541-A-202	XWVM
5541-A-202	VA3Y	5541-A-202	WOYL	5541-A-202	XGDX	5541-A-202	XYGP
5541-A-202	VBGT	5541-A-202	WPJT	5541-A-202	XGDY	5541-A-202	XYGR
5541-A-202	VGGG	5541-A-202	WRXC	5541-A-202	XIJC	5541-A-202	YBCC
5541-A-202	VJHG	5541-A-202	WRYC	5541-A-202	XKSY	5541-A-202	YBCD
5541-A-202	VJYO	5541-A-202	WSDE	5541-A-202	XKSZ	5541-A-202	YESI
5541-A-202	VPBW	5541-A-202	WVWI	5541-A-202	XOCL	5541-A-202	YFJX
5541-A-202	VPYA	5541-A-202	WVWJ	5541-A-202	XOCM	5541-A-202	YFJY
5541-A-202	VT43	5541-A-202	WXAV	5541-A-202	XTJY	5541-A-202	YG3H
5541-A-202	VUWT	5541-A-202	WXAW	5541-A-202	XTJZ	5541-A-202	YGSJ
5541-A-202	VVJG	5541-A-202	XAVX	5541-A-202	XVIO	5541-A-202	YGSK
5541-A-202	VW3E	5541-A-202	XAVY	5541-A-202	XVIP	5541-A-202	
5542-A-201	A3I7L	5542-A-201	BAX4A	5542-A-201	GLFE	5542-A-201	JMEP
5542-A-201	A4A7B	5542-A-201	BBG4X	5542-A-201	GYKA	5542-A-201	JPFR
5542-A-201	A4V7D	5542-A-201	BDR7T	5542-A-201	GZYI	5542-A-201	JTXL
5542-A-201	A7G7H	5542-A-201	BDZ4D	5542-A-201	GZZO	5542-A-201	JUEV
5542-A-201	A7H4U	5542-A-201	BE37Y	5542-A-201	HVFF	5542-A-201	KFSH
5542-A-201	A7L4V	5542-A-201	BGE4V	5542-A-201	HYZB	5542-A-201	KGWZ
5542-A-201	A7V3U	5542-A-201	BHE7X	5542-A-201	HZAP	5542-A-201	KIDM
5542-A-201	A9X4S	5542-A-201	BIG4L	5542-A-201	HZFF	5542-A-201	KIFY
5542-A-201	A9Y3V	5542-A-201	BR79T	5542-A-201	HZRR	5542-A-201	KION
5542-A-201	AAG7R	5542-A-201	BRU7O	5542-A-201	IDGA	5542-A-201	KJYX
5542-A-201	ABU3Y	5542-A-201	BSR4R	5542-A-201	IDXJ	5542-A-201	KMKE
5542-A-201	AEE3A	5542-A-201	DFHS	5542-A-201	IEYN	5542-A-201	KPKD
5542-A-201	AEU9Y	5542-A-201	DFOR	5542-A-201	IJPT	5542-A-201	KWXS
5542-A-201	AGT4R	5542-A-201	DGFY	5542-A-201	IKJU	5542-A-201	KZDA
5542-A-201	AGV3S	5542-A-201	DGJN	5542-A-201	IRIK	5542-A-201	LARN
5542-A-201	ALS3V	5542-A-201	DNNS	5542-A-201	ISIR	5542-A-201	LBMI
5542-A-201	AOG3T	5542-A-201	DPSK	5542-A-201	IULX	5542-A-201	MDIF
5542-A-201	AOX9L	5542-A-201	GEZU	5542-A-201	IWXH	5542-A-201	MMUR
5542-A-201	ASD3T	5542-A-201	GFBA	5542-A-201	IZXM	5542-A-201	S3O3
5542-A-201	ATT7D	5542-A-201	GFWO	5542-A-201	JAAE	5542-A-201	S3OP
5542-A-201	AV34S	5542-A-201	GGID	5542-A-201	JFWD	5542-A-201	ST3Y
5542-A-201	AYA3B	5542-A-201	GISR	5542-A-201	JFYR	5542-A-201	STHI
5542-A-201	AZB4R	5542-A-201	GITX	5542-A-201	JHWV	5542-A-201	STUE
5542-A-201	AZE9G	5542-A-201	GLDE	5542-A-201	JJDF	5542-A-201	TAOV
5542-A-201	BAE4X	5542-A-201	GLEK	5542-A-201	JLGH	5542-A-201	TARO



Catalog Number	Lot	Catalog Number	Lot	Catalog Number	Lot	Catalog Number	Lot
5542-A-201	TGLR	5542-A-201	WOOU	5542-A-201	XKLR	5542-A-201	YA3U
5542-A-201	UDYZ	5542-A-201	WPGU	5542-A-201	XXO	5542-A-201	YAIL
5542-A-201	UUZT	5542-A-201	WRZZ	5542-A-201	XXP	5542-A-201	YAIM
5542-A-201	UWHB	5542-A-201	WVWK	5542-A-201	XXR	5542-A-201	YCFT
5542-A-201	VEU4	5542-A-201	WVWL	5542-A-201	XSFR	5542-A-201	YCFV
5542-A-201	VJKA	5542-A-201	WXAC	5542-A-201	XSFS	5542-A-201	YFUX
5542-A-201	VJLN	5542-A-201	WXAF	5542-A-201	XVMV	5542-A-201	YFUY
5542-A-201	VVKR	5542-A-201	XBEL	5542-A-201	XVMW	5542-A-201	YGIC
5542-A-201	VVMJ	5542-A-201	XBEM	5542-A-201	XVNF	5542-A-201	YGID
5542-A-201	VW4Y	5542-A-201	XDXI	5542-A-201	XVNG	5542-A-201	YHLN
5542-A-201	VYAY	5542-A-201	XDXJ	5542-A-201	XWVH	5542-A-201	YHLO
5542-A-201	WHOP	5542-A-201	XIAR	5542-A-201	XWVI	5542-A-201	
5542-A-201	WINY	5542-A-201	XIAS	5542-A-201	XYUX	5542-A-201	
5542-A-201	WIVT	5542-A-201	XKLP	5542-A-201	XYVJ	5542-A-201	
5542-A-202	A3G9I	5542-A-202	BEL3L	5542-A-202	GZJM	5542-A-202	JORA
5542-A-202	A3L3E	5542-A-202	BEZ3G	5542-A-202	GZNW	5542-A-202	JUWH
5542-A-202	A494U	5542-A-202	BG34H	5542-A-202	GZSO	5542-A-202	JZWG
5542-A-202	A737R	5542-A-202	BGL3Y	5542-A-202	GZTX	5542-A-202	KDER
5542-A-202	A7O3V	5542-A-202	BLZ4V	5542-A-202	GZSN	5542-A-202	KDZP
5542-A-202	A9Z9I	5542-A-202	BO49D	5542-A-202	GZXP	5542-A-202	KEOH
5542-A-202	AB34V	5542-A-202	BOA3B	5542-A-202	HUTX	5542-A-202	KFXJ
5542-A-202	AEU3A	5542-A-202	BOX9G	5542-A-202	HWPX	5542-A-202	KGSW
5542-A-202	AEV4T	5542-A-202	BRG9O	5542-A-202	HXYV	5542-A-202	KJEK
5542-A-202	AGT3G	5542-A-202	BRV7A	5542-A-202	IBPA	5542-A-202	KJHN
5542-A-202	AGU9H	5542-A-202	BRY9V	5542-A-202	IBPG	5542-A-202	KKPN
5542-A-202	AH73U	5542-A-202	BSR7E	5542-A-202	IDXU	5542-A-202	KLXZ
5542-A-202	AHE9A	5542-A-202	BSS4B	5542-A-202	IKKL	5542-A-202	KSGD
5542-A-202	ALS7R	5542-A-202	BTB3H	5542-A-202	IKUD	5542-A-202	KSPF
5542-A-202	AOG7L	5542-A-202	DGKJ	5542-A-202	IMUI	5542-A-202	KTLH
5542-A-202	ARD3S	5542-A-202	DGSH	5542-A-202	ISHW	5542-A-202	KUAI
5542-A-202	ASS9S	5542-A-202	DIXP	5542-A-202	IXVN	5542-A-202	KUKW
5542-A-202	ASU7H	5542-A-202	DKAX	5542-A-202	IYSN	5542-A-202	KYBZ
5542-A-202	ATY7Z	5542-A-202	FYPO	5542-A-202	IZUI	5542-A-202	LBAM
5542-A-202	AXZ3G	5542-A-202	FYRV	5542-A-202	JBSB	5542-A-202	LBFD
5542-A-202	AY37S	5542-A-202	GFMT	5542-A-202	JBXN	5542-A-202	MBZM
5542-A-202	BAS4A	5542-A-202	GJLZ	5542-A-202	JHAF	5542-A-202	MDBV
5542-A-202	BBX7R	5542-A-202	GJNG	5542-A-202	JHGV	5542-A-202	MERR
5542-A-202	BDV9H	5542-A-202	GLDO	5542-A-202	JJFK	5542-A-202	MFSR



Catalog Number	Lot	Catalog Number	Lot	Catalog Number	Lot	Catalog Number	Lot
5542-A-202	MIRW	5542-A-202	WIWZ	5542-A-202	XIJA	5542-A-202	XYHM
5542-A-202	MMLL	5542-A-202	WRTS	5542-A-202	XKIW	5542-A-202	XYHN
5542-A-202	SZSR	5542-A-202	WRXX	5542-A-202	XKIX	5542-A-202	YBDF
5542-A-202	TROU	5542-A-202	WTDT	5542-A-202	XNAC	5542-A-202	YBDG
5542-A-202	TRVH	5542-A-202	WVVP	5542-A-202	XNBF	5542-A-202	YCEY
5542-A-202	UEYI	5542-A-202	WVZC	5542-A-202	XNCN	5542-A-202	YCEZ
5542-A-202	UHER	5542-A-202	WXBU	5542-A-202	XRBV	5542-A-202	YCZV
5542-A-202	UZIY	5542-A-202	WXBV	5542-A-202	XRBW	5542-A-202	YCZW
5542-A-202	VETP	5542-A-202	WXBW	5542-A-202	XTAS	5542-A-202	YFCI
5542-A-202	VJMC	5542-A-202	WXPB	5542-A-202	XTAT	5542-A-202	YFCJ
5542-A-202	VJOS	5542-A-202	WXPJ	5542-A-202	XVHZ	5542-A-202	YGJM
5542-A-202	VUWS	5542-A-202	WXPJ	5542-A-202	XVMM	5542-A-202	YGJN
5542-A-202	VVCY	5542-A-202	XBEH	5542-A-202	XVMN	5542-A-202	YHHU
5542-A-202	VVDW	5542-A-202	XBEI	5542-A-202	XVNA	5542-A-202	YHPT
5542-A-202	WHDY	5542-A-202	XDBP	5542-A-202	XXIW	5542-A-202	YHPU
5542-A-202	WISW	5542-A-202	XDBR	5542-A-202	XXIX	5542-A-202	